

HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS

HAER
SD
52-RACIV,
9-

ST. GERMAIN DITCH
Lower Rapid Valley Irrigation Ditches
On the North Side of Rapid Creek
Caputa Vicinity
Pennington County
South Dakota

HAER No. SD-10

Ron Seirs and Chuck Erickson, photographers, September 1993

- SD-10-1 ST. GERMAIN DITCH HEADGATE. DOWNSTREAM SIDE. VIEW TO WEST.
- SD-10-2 ST. GERMAIN DITCH HEADGATE HANDWHEEL.
- SD-10-3 ST. GERMAIN DITCH MARSH (WEST) TURNOUT AT LINE BETWEEN SECTIONS 5 AND 6, T1S, R1 E. VIEW TO EAST-SOUTHEAST.
- SD-10-4 ST. GERMAIN DITCH CANAL NEAR MIDDLE OF SOUTH SECTION LINE, SE ¼, SECTION 35, T1N, R9E. VIEW TO NORTHWEST.